

2883 Breakers Ct. Fernandina Beach, FL 32034

www.mccalltree.com (904) 557-3951

November 16, 2018 (Revised June 25, 2019)

Property Owners: Forum Capital Partners LLC c/o Morgan Brown 9995 Gateway N. Suite 400 Jacksonville, FL 32034

Subject: Inspection, certification, and calculations of trees to satisfy the Nassau County Tree ordinance requirements for the new proposed Enclave Beach Access from Enclave I to Amelia Island Parkway

Attached are the calculations to satisfy the Nassau County Tree Protection Ordinance Section 37.02 of the Land Development Code (LDC) currently in force. Tree numbers on the spreadsheet correspond to numbers from the survey provided to me and on the plans. According to the calculations acceptable to Nassau County, 72% of the diameter at breast height (dbh) of the trees presently on the site will be saved. That is 27 percentage points more than the present requirement of 45%

Trees with a red "M" in the saved column will be "maintained" which means that they will remain on the site, but not officially count toward trees saved. Even though the path may encroach on the TPZ of these trees somewhat, the owner would like to keep as many trees as possible to enhance the aesthetic value and maintain canopy.

Barricades will be established for this project as a required by Nassau County LDC Section 37.02(G). The contractor should let me know when the barricades have been established around the trees so that I can inspect them to report back to Nassau County officials that barricades are correctly established. Barricades should be constructed according to requirements contained in the definition of "Barricades" in Article 32 Definitions.

A drainage system to disperse water from the trail will consist of a 6" perforated pipe covered by filter fabric and course aggregate parallel to the trail on the downward sloping side. Sidewalks/multi-use paths may sometime be within the TPZ, but are at least three times the diameter of any tree on the property as suggested by the Special Companion Supplement to the ANSI A300 Standards Practices Part 8 - Root Management, I do not expect significant impact on existing trees. The path will be at least 3 feet away from any saved tree on the plan. The path will be constructed for MUP and light duty traffic with 12" Type B 12" stabilization layer, a 5.5" SP Base Course and 1" asphalt wearing surface.

Kindest regards.

Early McCall


ISA Certified Arborist FL-6200A ISA Tree Risk Assessment Qualified



ARBORJET

TREE PROTECTION BARRICADE DETAIL

DESCRIPTION



THE TREE PROTECTION BARRICADE SHALL BE AT LEAST THREE (3) FEET HIGH. THE BARRIER SHALL CONSIST OF EITHER WOOD FENCE WITH 2x4 POSTS PLACED A MAXIUM OF EIGHT (8) FEET APART, WITH A 2x4 TOP RAIL OR A TEMPORARY WIRE MESH FENCE, OR OTHER SMILAR BARRIER WHICH WILL LIMIT ACCESS TO PROTECTED AREA.

THE BARRIER SHALL BE AT LEAST ONE FOOT IN DIAMETER FOR EVERY INCH OF TRUNK DIAMETER. FOR TREES LESS THAN 12" DBH, THE MINIMUM BARRIER SHALL BE AT LEAST SIX (6) FEET AWAY FROM THE BASE OF THE TREE.

TREE BARRICADE APPROVAL: OBTAIN CITY APPROVAL OF TREE BARRICADE BEFORE BEGINNING CLEARING OPERATIONS OR ANY SITE DEVELOPMENT.

REVISIONS

	001850 x
	福行
	7/10

DESCRIPTION

McCall Tree Health and Consulting LLC 2883 Breakers Ct.

22

11

11

14

12

14

10

22

22

14

23

130

131

133

136

137

139

140

141

142

143

150

152

153

154

155

156

157

158

271

272

273

274

275

277

LO

LAU

LO

LAU

LAU

LAU

LAU

LAU

LAU

LAU

LO

LAU

LO

LO

LAU

LAU

LAU

MAG

MAG

LO

LO

LO

LAU

3

4

4

3

5

4

www.mccalltree.com Fernandina Beach, FL 32034 (904) 557-3951

ENCLAVE AT SUMMER BEACH HOA

PROJECT NAME PHASE 1 ORANGE AVENUE PATH

27.5 dead wood

forked

forked

severe lean

rubbing on 152

rubbing on 153

clean vines crooked from

competition

crooked

27.5 forked at base

28.75 multiple splits

0 top out dead

0 dieback and hollow

clean vines

internal decay

forked at base

trim deadwood

crook in the stem

crooked

lean

11

11

0

10

0

14

18

10

14

16

Ω

N

Ν

Ν

Ν

26.25

14

12

14

27.5

28.75

16

ARBORIST REPORT TREE PROTECTION DETAIL / NOTES SHEET NO.

Arborist

Project Enclave Beach Access Bonus Al Protected Native Canopy Trees (table 37-4 trees 6" or greater) Percentile M = Maintained

Species does not count To be removed for health

Tree #	size (dbh)	Species	Status	with bonus	saved? (Y/N)	saved dbh	n Comment								
							poor crown	278		LAU	5	0	N	0	decay in stem
44							competition, decay	279	10	CHY	2	10	Υ	10	crooked base
	16	LAU	3	16	Υ	16	at base	000							leans from
45							dead limb fell out,	280	25	LO	2	31.25	Υ	31.25	competition
45		Camphor	5	l ol	Ν	0	poor tree	284	14	LAU	2	14	Y	14	some dieback
46	41	LÖ	1	51.25	Y	51.25	ľ								crooked, hole at 2
48		LAU	5	0	N	0	hollow	285	12	LO	2	12	Υ	12	feet
58	17	LAU	1	17	M	0		288	20	LO	3	25	Y	25	dead fork at 5 feet
							poor crown from			1				 	trim off dead wood
59	9	LAU	2	9	Ν	0	competition	289	14	LO	3	14	Υ	14	at 3 feet
60	13	LAU	1	13	N	0		290	17	LO	1	17	Y	17	
62	11	LAU	3	11	N	0		291		LO	4	0	N .	0	crown out
							part of crown fell			1		-		 	almost dead,
72	27	LO	3	33.75	Ν	0	out	292		LO	5	ol	N	0	decay, split
				33.13	.,		broken crown, split	313		LO	5	0	N	0	top out
82		LO	4	o	Ν	0	stem	316	10	LAU	1	10	Y	10	100 000
83	15	LO	1	15	N	0	0.000	317	15	LAU	2	15	M	0	crooked
85	12	LAU	2	12	Y	12	bent somewhat	322	13	LO	1	13	Y	13	
91	12	LAU	1	12	Y	12	needs vine cleanup	323		LO	4	0	N .	0	top out
	· -				•	·-	forked, small hole			1		-		 	some dead wood.
92	25	LO	2	31.25	N	0	at base	324	8	LO	2	8	Υ	8	lean
93	22	LO	1	27.5	N	0	3.0 .0 .0 .0			1				<u> </u>	crown poor growing
94	15	LAU	1	15	Y	15		325		LO	4	ol	N	0	into water oak
95	18	LO	1	18	Y	18		327	13	LO	3	13	N	0	forking, lean
96	9	Н	3	9	Y	9	poor crown	690	15	Н	3	15	Υ	15	severe bend
101	9	LAU	2	9	Υ	9	Phyto	691	18	LAU	1	18	N	0	
102	8	LAU	1	8	N	0	,	000							crooked from
400							severe lean, near	692	10	LAU	3	10	Ν	0	competition
103	9	LAU	3	9	Ν	0	road	693	18	LAU	1	18	М	0	'
104	10	LAU	2	10	N	0	forked crown	694	18	LAU	2	18	М	0	some dead limbs
							limb fell off, some	005							multiple forks,
108	20	LO	2	25	М	0	splits	695		LO	5	ol	Ν	0	minimal crown
112	11	LO	3	11	Y	11	forked with 113	697	16	LAU	1	16	Υ	16	
113	15	LO	3	15	Υ	15	forked with 112	000							really 8 inches,
114		LO	4	0	N	0	top out	698	8	н	2	8	M	0	crooked
117		Water Oak	1	0		0	<u> </u>	699		LAU	4	0	N	0	decay
118		LO	4	0	N	0	top out	700	18	LO	1	18	Υ	18	,
							clean some dead	787		Water Oak	1	0		0	
120	18	LO	2	18	Υ	18	wood	788	19	LO	3	19	Υ	19	forked, split
126	24	LO	2	30	Y	30	some dead wood	789	10	LO	1	10	Y	10	
127	20	LO	1	25	Y	25									
							tree hung up in this					1116.5			
128							live oak, some								
		I	1	i l		1	1 '								

Percentile Bonus Size

Pre-dev dbh

% dbh saved

dbh saved

required

difference

am a certified arborist through the International Society of Arboriculture and my certification number is_ attest that I have prepared this tree protection and replacement plan and/or restoration plan. This includes not only the evaluation of individual trees but also review of the complete construction plan set and the techniques that will be utilized to mitigate impacts to protected trees. Further, I attest that best practices, as supported by the International Society of Arboriculture, are being implemented to avoid and mitigate impacts to protected trees.

TREE BARRICADE INSPECTION NOTES:

1. TREE PROTECTION BARRICADE DETAIL: CONTACT THE NASSAU COUNTY DEPARTMENT OF PLANNING & ECONOMIC OPPORTUNITY FOR TREE BARRICADE INSPECTION AND APPROVAL BEFORE BEGINNING TREE CLEARING OPERATIONS.

19.6

1033

743.75

72%

45%

-27%

- 2. PRIOR TO ANY CLEARING, THE MARKED TRAIL SHALL BE WALKED BY PEO STAFF AND BY Ms. JORDI (UF/IFAS ARBORIST) IN ORDER TO CLEARLY MARK THE TREES TO BE SAVED.
- 3. TREE BARRICADES ARE REQUIRED PER SEC. 37.02(G) AND ARTICLE 32 DEFINITIONS IN THE NASSAU COUNTY LAND DEVELOPMENT CODE.